

### **Y axis transmission adjustment**

Symptom: Head alignment is still not lining up after going through the head adjustment procedure.

Tools Required:

5/64" Hex wrench

Tighten the setscrews shown on the Y axis transmission

