

Technical Bulletin

Force Adjustment Cam Replacement/SmarTrac

This procedure requires 2 people positioned at the front and rear of the SmarTrac Signcutter.

- 1. From the rear of the machine rotate the force adjustment cam slot to the vertical position with a flat head screwdriver (24-lb. setting).
- 2. From the front of the machine have your assistant reach over the top cover and lift the spring-loaded bracket at the points illustrated in *Fig 1*.
- 3. Remove the cam by pulling it straight out of the square hole as illustrated in *Fig 2* (rotate if necessary).
- 4. Insert the new cam.
- 5. Your assistant can then release the spring-loaded bracket.

